

## Item 9 - Climate Change Working Party - Monday 26 October 2020





**Photograph 3:**  
Fencing near Full Pitcher end of the town trail, posts are rotted away.



**Photograph 4:**  
Steps to Little Marcle Road, end of the Riverside Walk, these have been broken for a very long time.



**Photograph 5:**

**Fencing along Riverside Walk; Balfour Beatty have just recently repaired the fencing and gate at the Hereford Road end of the Riverside Walk ,they ignored the broken fence shown in photo 5 which is just along the road ,**

**Balfour Beatty have just recently done much clearance and cutting back of overgrowth along the Riverside Walk, a great improvement . One day's work with the same machine on the town trail would be great. Balfour Beatty have the machinery and it would make it very much easier to keep this area under control in future**



**Photograph 6:**

**Fencing on Recreation Ground; broken for a very long time**